Data Erasure Report

blancco

Licensed To	HGH Services
Customer Details	Customer Name: Number 8 Bid
Operator Details	Erasure Provider: HGH Services Erasure Technician: Ash

Custom Fields

Job #:   1016963

Erasure Results

Disk: 1 (1-1)

Vendor: **SAMSUNG**	Model: **MZ7LN256HCHP-000L7**	Serial: **S20HNCAH208860**
Size: **256GB**	Bus: **SATA/SSD**	Sectors: **500118192**
HPA: **Doesn't exist**	DCO: **Doesn't exist**	Remapped Sector(s): **0**
Health Status: **good**		

(barcode)

Remapped Sector(s) After Erasure:	**0**
Start/End Time:	**2020-08-06 00:29:28 (+0000) / 2020-08-06 01:09:43 (+0000)**
Duration:	**00:40:14**
Method:	**Blancco SSD Erasure - ATA**
Erasure Rounds:	**4 (2 overwriting, 2 firmware based erasure)**
Status:	**Erased**
Information:	**Device is SSD, see manual for more information.**

Hardware Details

Manufacturer:	LENOVO
Chassis Type:	Notebook
Model:	20FM0037AU
Serial:	PC0B9VQC
UUID:	78b85f4c-2b49-11b2-a85c-fe03b091a811
Asset Tag:	No Asset Information
System Version:	ThinkPad T460
System SKU Number:	LENOVO_MT_20FM_BU_Think_FM_ThinkPad T460
Processor:	GenuineIntel, Intel(R) Core(TM) i5-6300U CPU @ 2.40GHz, Cores: 2, Stepping: 3, Nominal speed: 2400MHz, Max speed: 3000MHz, External Clock: 100 MHz, Voltage: 1.0 V
Memory Bank:	Unknown Vendor, Empty slot, SODIMM
Memory Bank:	SK Hynix, 8192MB, 1600MHz, DDR3, SODIMM, Serial: 1221CBBF
Total Memory:	8192MB, Occupied memory banks: 1/2
Graphics Card:	Intel Corporation Skylake GT2 [HD Graphics 520], 32MB System memory reserved by EFI/BIOS
Current Resolution:	1366x768
Sound Card:	Intel Corporation Sunrise Point-LP HD Audio
Storage Controller: 1	Intel Corporation Sunrise Point-LP SATA Controller [AHCI mode]
Disk: 1 (1-1)	SAMSUNG, MZ7LN256HCHP-000L7, Firmware: EMT03L6Q, Serial: S20HNCAH208860, 256GB / 500118192 sector(s), SATA/SSD, Sector Size: 512, Average Write Speed: 292MB/s, Average Read Speed: 467MB/s, Accessible Region: 256GB / 500118192 sector(s), DCO: Doesn't exist, HPA: Doesn't exist, Health Status: good
Network Adapter:	Ethernet, Intel Corporation Ethernet Connection I219-LM
Network Adapter:	Wireless, Intel Corporation Wireless 8260
USB Device:	Intel Corp., Unknown model (0x0a2b) 2.00
USB Device:	Acer, Inc, Unknown model (0x0706), SunplusIT Inc, Integrated Camera 2.00
USB Device:	Silicon Motion, Inc. - Taiwan (formerly Feiya Technology Corp.), Flash Drive 2.00
Motherboard:	LENOVO, 20FM0037AU
BIOS:	LENOVO, Version: R06ET67W (1.41), Date: 05/07/2019
BIOS Features:	PCI, PNP, ACPI, CD Boot, EDD, Legacy USB
Ports:	USB Ports: 3, Ethernet: 1
Battery: 1	Vendor: LGC, Model: 45N1127, Serial: 3948, Type: Li-ion, Capacity: 18970 / 23480 mWh, Voltage:12543 mV
Battery: 2	Vendor: LGC, Model: 45N1113, Serial: 11320, Type: Li-ion, Capacity: 20630 / 23480 mWh, Voltage:11449 mV

Hardware Check

Battery: 1	Successful (Capacity: 80%)	Battery: 2	Successful (Capacity: 87%)
Motherboard:	Successful	Memory:	Successful (Passes: 3)
	○ RTC test passed		

- DMI test passed
- CMOS battery test passed
- CMOS checksum test passed

CPU:	Successful	Pointer:	Successful
Display:	Successful	Keyboard:	Successful
PC Speaker:	Successful	Webcam:	Successful
Wi-Fi Adapter:	Successful	Battery Discharge:	Successful
			- 0min 0s 100% -> 100%

Report Details

Report UUID:	24278f65-d3c5-4bd8-9e2c-d7ff81d352cb
Report Date:	2020-08-06 01:09:49 (+0000)
Software Version:	Blancco Drive Eraser 6.13.1
Digital Signature:	

JIdpp5BzkCnFNM6W1BiZLX7wpygY/mCz9kCB6p1UeVBek62tGHS3F3v4eSGGhHhgYb8Ep6+P/KfeN+EB2m9NJDLbxV46S4U1JyZngX+TMng/AqW61D0jIvHkzF+9HCFnPJ3c88JcfnJcL1AFwLdxIKzreV3JM0wOaNIL2IDdQftuQS
7SuWoOshGhKoyPNq74KV4evrfAh3fWidHXHO05XvYWXtmorRs4bV+rTKA4F/PnqA8QVIFeVNUa8865qFimN9QGOGR5IP4ePk9CqvBS7iYVsilLgdCHLxMaOFxNRPTVS+A+c05jDcLCvKOGhKCcTcscUPAfAh0Cmyhru5NiVw==

I hereby state that the data erasure process has been carried out in accordance with the given instructions.

_____   _____
DATA ERASURE OPERATOR   SUPERVISOR